

平成 30 年台風 21 号。西日本豪雨被害・復旧状況

2018.12.30



2018.7.9 夜泣き峠崖崩れ注意表記(下川・北川・伊佐) 同左崖崩れ



2018.07.11 上の水峠崩落

2018.7.11 上の水峠通行止めと迂回路設置



2018.9.9 大文字への道倒木



2018.9.11 高雄～苔寺被害調査・処置(竹内)



2018.9.11 高雄～清滝陥没(竹内)



2019.1.31 同左修理(竹内・宇野)



2018.9.12 嵐山～苔寺・四つ辻被害(岡田)



2018.9.12 清水山唐綿神社被害状況(通報)



2018.9.13 蹴上～北白川倒木処置(西組)



2018.9.13 比叡山～曼衆院倒木処置(東組)



2018.9.13 日向神社～東山 34 階段処置後(西組)



2018.9.13 東山 35 伐採作業中(処理完了)



2018.9.15 盗人谷被害調査パトロール(中川)



同左・長谷川～上の水被害状況



2018.9.17 伏見桃山城外周道路電柱倒壊



2018.9.17 大岩神社倒木(北川・真田)



2018.9.18 嵐山倒木処置後(西組)



2018.9.18 嵐山～苔寺被害(西組)



2018.9.18 北白川～曼衆院倒木被害(東組)



2018.9.26 尊勝院～京女の森標識No.21～20 倒木



同左処置後(東組)



2018.9.26 蹴上～稲荷倒木処置(東組)



2018.10.17 鹿ヶ谷倒木



2018.10.17 鹿ヶ谷倒木処置完了



2018.10.30 二ノ瀬～山幸橋倒木処置(東組)



2018.11.8 日向神社ルート倒木(混合)テレビ朝日報道ステーション取材



2018.11.29 氷室～山幸橋倒木処置(全員)



2018.11.29 氷室～山幸橋橋補強(全員)



2018.12.6 嵐山 No.26～27 倒木(西組)



2018.12.6 嵐山 No.26～27 倒木処置後



2018.12.6 氷室～山幸橋倒木処置(東組)



2018.12.13 東山山頂公園～今熊野処置前



2018.12.13 同左処置後(西組)



2018.12.13 蹴上～北白川倒木処置(東組)